

Storrington Ditch Improvements
VOCHOA 2014



Photo #1: Placed straw matting and flex-a-mat within the finished ditch grades.



Photo #2: The culverts was originally 50% blocked prior to excavation. Placed flex-a-mat below the culvert outlet for erosion control.



Photo #3: Placed straw matting within the finished ditch grades.



Photo #4: Placed straw matting and flex-a-mat within the finished ditch grades.